

Profile/Ph	oto Observatio	n Report				RedZon
Date:	04/13/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	:): 292.7	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Cost	ello	PSR:	P-806-031-032
Customer:		Clean Date	: 01/01/1	900	Shape:	С
Street:	SPRINGDALE DR		Flow Cont	rol:	Not Controlled	
City:	Hobart, IN		Year Rene	ewed:		
Location:	Ditch		Tape/Me	dia #:		
Purpose:	Maintenance Rela	ated	Dia/Heigh	it:	8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:		Cured in Place	
Category:	NA					
Comment:						
Location Detai	ls:		Direction	of Survey:	Upstream	
US MH:	M-806-032	DS MH:	M-806-031	T	otal Length Surveyed (ft)	: 294.0
0&M Index:	0.00	O&M Quick		0000	O&M Rating:	0.00
tructural Index	0.00	Structural C		0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui	ck:	0000	Overall Rating:	0.00

	Position	Code	Observation	Video (sec)	Grade
M(806-	031				
\rightarrow	0.	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	64.9	TF	Tap Factory	163	NA
	70.9	TF	Tap Factory	188	NA
	// 146.5	TFA	Tap Factory Active	351	NA
	/ 150.6	TFA	Tap Factory Active	371	NA
	227.0	TFA	Tap Factory Active	536	NA
	232.5	TFA	Tap Factory Active	558	NA
	283.9	TF	Tap Factory	673	NA
5	286.4	TFA	Tap Factory Active	690	NA
ecti	294.0	AMH	Manhole	716	NA
Camera Direction					
M(806)					




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-806-031




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory	
Distance (ft):	64.9	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:	3	
Clock To:		
1st Value:	4.000	
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:		
Remarks:		




Code:	TF
Description:	Tap Factory

Distance (ft):	70.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TFA
Description:	Tap Factory Active
Distance (ft):	146.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code: Description: TFA Tap Factory Active


Distance (ft):	150.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Within 8" of Joint:

Remarks:




Code:	TFA
Description:	Tap Factory Active
	227.0
Distance (ft):	227.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	



Code:TFADescription:Tap Factory Active

Distance (ft):	232.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



TF Tap Factory
283.9
0
0
3
4.000



Code: Description: TFA Tap Factory Active

Distance (ft):	286.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	294.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-806-032