## **Profile/Photo Observation Report**



Date: 04/10/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 383.4 Owner: NA Pre Clean: **Not Known** P.O.#: **Mark Ruby** PSR: P-807-001-002 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: **E 12TH ST** Flow Control: **Not Controlled** 

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA


Comment: flow incorrect.

Location Details: Direction of Survey: Downstream

US MH: M-807-002 DS MH: M-807-001 Total Length Surveyed (ft): 378.1


0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Code:



Description:		Manhole
Distance (ft):		.0
Structural Gra	ade:	0
O&M Grade:		0
Clock Start/Fr	om:	
Clock To:		
1st Value:		
2nd Value:		
Value Percent	t:	
Continuous Ir	ndex:	
Within 8" of J	oint:	NO
Remarks:		M-807-002

AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO

4.000



Code: **TF** 

Description: Tap Factory

Distance (ft): 7.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2


Clock To:

Remarks:

1st Value: 2nd Value:

Value Percent:
Continuous Index:
Within 8" of Joint:

Thursday, November 16, 2023



Code: **TF** 

Description: Tap Factory


Distance (ft): 45.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 101.4
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TF

Description: **Tap Factory** 


146.8 Distance (ft): Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TS


Description: **Tap Saddle** 

Distance (ft): 209.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

4.000 1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF** 

Description: Tap Factory

Distance (ft): 285.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active


Distance (ft): 334.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:



Code: **TF** 

Description: Tap Factory


Distance (ft): 340.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 374.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 7

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: AMH
Description: Manhole

Distance (ft): 378.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-807-001