Profile/Photo Observation Report



Date: 03/21/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 103.8 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-808-005-004 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: CAPITOL DR Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Sidewalk Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA
Comment: flow direction incorrect.

Location Details: Direction of Survey: **Downstream**

US MH: M-808-004 DS MH: M-808-005 Total Length Surveyed (ft): 100.0

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Position	Code	Observation	Video (sec)	Grade
1(808-)004				
0.	AMH	Manhole	10	NA
.0	MWL	Water Level	21	NA
31.1	TF	Tap Factory	95	NA
100.0	AMH	Manhole	244	NA

Code:



Description:	Manhole		
Distance (ft): Structural Grade:	.0 0		
O&M Grade: Clock Start/From:	0		
Clock To: 1st Value:			
2nd Value: Value Percent: Continuous Index:			
Within 8" of Joint: Remarks:	NO M-808-004		

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000


Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: **TF**

Description: Tap Factory



Distance (ft): 31.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 1

Clock To:

Remarks:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: AMH
Description: Manhole

Distance (ft): 100.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-808-005