## **Profile/Photo Observation Report**



Date: 03/21/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 136.7 Owner: NA Pre Clean: **Not Known** P.O.#: P-808-012-011 PSR: Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: Oak Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Sidewalk Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA

Comment: flow direction

Location Details: Direction of Survey: Downstream

US MH: M-808-011 DS MH: M-808-012 Total Length Surveyed (ft): 133.3

1.50 2111 3.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 1.50 2111 3.00 Overall Index: Overall Quick: Overall Rating:

Position	Code	Observation	Video (sec)	Grade
808-011				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
21.3	TFD	Tap Factory Defective	76	M 2
21.3	RFL	Roots Fine Lateral	87	M 1
84.0	TF	Tap Factory	224	NA
133.3	AMH	Manhole	335	NA

Code:



Description:	Manhole	
Distance (ft): Structural Grade:	.0 0	
O&M Grade: Clock Start/From:	0	
Clock To: 1st Value:		
2nd Value: Value Percent: Continuous Index:		
Within 8" of Joint: Remarks:	NO M-808-011	

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: **TFD** 

Description: **Tap Factory Defective** 

Distance (ft): 21.3 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 1

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: rfl



Code: RFL

Description: Roots Fine Lateral

Distance (ft): 21.3
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 1

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF** 

Description: Tap Factory

Distance (ft): 84.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

2nd Value:

1st Value: **4.000** 

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 133.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-808-012