Profile/Photo Observation Report



P-808-026-027

PSR:

Date: 03/22/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 395.4 Owner: NA Pre Clean: **Not Known** P.O.#:

Selasie Honu

Customer: Clean Date: 01/01/1900 Shape:

S HOBART RD Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Ditch Tape/Media #: Location:

Purpose: **Maintenance Related** Dia/Height: 12" Use: Sanitary Material: **PVC**

NΑ Drain Area: Lining:

NA Category: Comment: sludge on sidewall at 314'.

Location Details: Direction of Survey: Upstream

US MH: M-808-026 M-808-027 Total Length Surveyed (ft): DS MH: 315.4

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

| Position | Code | Observation | Video (sec) | Grade |
|---------------------------------------|------|------------------|-------------|-------|
| VI (808 -)027 | | | | |
| .0 | AMH | Manhole | 10 | NA |
| 0. | MWL | Water Level | 21 | NA |
| 315.4 | MSA | Abandoned Survey | 663 | NA |
| | | | | |

Code:



| Description: | Manhole | |
|---|-----------------|--|
| Distance (ft): Structural Grade: | .0 0 | |
| O&M Grade: Clock Start/From: | 0 | |
| Clock To: 1st Value: | | |
| 2nd Value: Value Percent: Continuous Index: | | |
| Within 8" of Joint: Remarks: | NO M-808-027 | |
| | | |

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: MSA

Description: **Abandoned Survey**



Distance (ft): 315.4

Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped