## **Profile/Photo Observation Report**



Date: 03/22/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 395.4 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-808-026-027

Selasie Honu

Customer: 01/01/1900 Clean Date: Shape:

Oak Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed: Ditch Tape/Media #: Location:

Purpose: **Maintenance Related** Dia/Height: 12" Sanitary Use: Material: **PVC** 

Surveyor:

NΑ Drain Area: Lining:

NA Category: Comment: sludge on sidewall at 314'.

**Location Details:** Direction of Survey: Upstream

US MH: M-808-026 M-808-027 Total Length Surveyed (ft): DS MH: 315.4

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Posit	ion Code	Observation	Video (sec)	Grade
M-808-027				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
315.4	MSA	Abandoned Survey	663	NA
Camera Direction  M(808)026				

Code:



Description:	Manhole	
Distance (ft): Structural Grade:	.0 0	
O&M Grade: Clock Start/From:	0	
Clock To: 1st Value:		
2nd Value: Value Percent: Continuous Index:		
Within 8" of Joint: Remarks:	NO M-808-027	

AMH



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: MSA

Description: **Abandoned Survey** 



Distance (ft): 315.4

Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped