Profile/Photo Observation Report



Date: 04/05/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 391.8 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-808-029-030 Surveyor: Jen Costello

Customer: Clean Date: 01/01/1900 Shape: C

Street: Hobart Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Ditch Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: Flow direction wrong. Reverse setup.

Location Details: Direction of Survey: **Downstream**

US MH: M-808-030 DS MH: M-808-029 Total Length Surveyed (ft): 7.4

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:


Position	Code	Observation	Video (sec)	Grade
808-030				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
7.4	MSA	Abandoned Survey	47	NA
808-029				

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade: O&M Grade:	0 0	
Clock Start/From: Clock To:		
1st Value: 2nd Value:		
Value Percent: Continuous Index:		
Within 8" of Joint: Remarks:	NO M-808-030	

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO



Code: MSA

Description: **Abandoned Survey**

Distance (ft): 7.4 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: unknown