Profile/Photo Observation Report



Date: 03/24/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 99.9 Owner: NA Pre Clean: **Not Known**

P.O.#: **Byrd Fitzgerald** PSR: P-809-009-010 Surveyor: Customer: Clean Date: 01/01/1900 Shape:

GROSBEAK CT Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed:

Ditch Tape/Media #: Location: Purpose: **Maintenance Related** Dia/Height:

8" **PVC** Use: Sanitary Material:

NΑ Lining: Drain Area: NA

Comment: Reverse, user set max at 65'.

Category:

Location Details: Direction of Survey: Upstream

US MH: M-809-009 M-809-010 Total Length Surveyed (ft): DS MH: 66.6

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
309-010				
0.	AMH	Manhole	10	NA
0. //	MWL	Water Level	21	NA
2.5	TF	Tap Factory	38	NA
\ 4.8	TF	Tap Factory	55	NA
40.0	TF	Tap Factory	138	NA
66.6	MSA	Abandoned Survey	203	NA

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-809-010	

AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:

Value Percent: **5.000**Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TF
Description: Tap Factory

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 4.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:


1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 40.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2


Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 66.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: no blockage