

Profile/Ph	noto Observation	n Report				RedZon R 0 B 0 T I C S
Date:	03/22/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	t): 375.1	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Ho	onu	PSR:	P-809-025-022
Customer:		Clean Date	: 01/01/19	00	Shape:	с
Street:	LIBERTY ST		Flow Contr	ol:	Not Controlled	
City:	Hobart, IN		Year Renev	ved:		
Location:	Sidewalk		Tape/Medi	a #:		
Purpose:	Maintenance Rela	ated	Dia/Height	:	8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detai	ils:		Direction o	f Survey:	Downstream	
US MH:	M-809-025	DS MH:	M-809-022	Тс	otal Length Surveyed (ft)	367.4
0&M Index:	0.00	O&M Quick	:	0000	O&M Rating:	0.00
tructural Index	. 0.00	Structural Q	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quid	~k·	0000	Overall Rating:	0.00





Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-025




Code: MWL Description: Water Level

.0
0
0
5.000
NO




Code:	MGO	
Description:	General Observation	

225.8
0
0
NO
switching to rear camera



Code:	TF
Description:	Tap Factory
	220.0
Distance (ft):	228.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	239.5 0 0 2 4.000
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	367.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-022