Profile/Ph	oto Observatio	n Report				RedZone
Date: Pipe Length (ft P.O.#:	03/22/2018 :): 214.3	Weather: Owner: Surveyor:	NA Selasie Honu		Coding: Pre Clean: PSR:	PACP 6.0 Not Known P-809-024-025
Customer:		Clean Date:	01/01/1900		Shape:	C
Street:	MURRELET ST & LIBERTY ST		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Sidewalk		Tape/Media #:			
Purpose:	Maintenance Rel	ated	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	mh confirmed. flo	ow direction inco	rrect.			
Location Detai	ls:		Direction of Su	rvey:	Downstream	
US MH:	M-809-025	DS MH:	M-809-024	Total	Length Surveyed (ft)	: <b>214.5</b>
O&M Index:	2.00	O&M Quick:	21	00	O&M Rating:	2.00
Structural Index:	0.00	Structural Q	uick: 00	00	Structural Rating:	0.00
Overall Index:	2.00	Overall Quic	k: 21	00	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
M(809-)0	25				
$\leq$	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	\3.3	MGO	General Observation	41	NA
	78.0	TFA	Tap Factory Active	206	NA
	79.6	TF	Tap Factory	224	NA
	137.2	TF	Tap Factory	355	NA
	157.6	TFA	Tap Factory Active	411	NA
	197.0	TF	Tap Factory	504	NA
	206.7	TFA	Tap Factory Active	538	NA
5	208.5	TF	Tap Factory	556	NA
ecti	211.7	DSZ	Deposits Settled Other	578	M 2
ă	214.5	AMH	Manhole	598	NA
Camera Direction					
M(809)0	24				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-025




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	MGO General Observation
Distance (ft):	3.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	switching to rear view




Code: TF Description: Ta

TFA Tap Factory Active

Distance (ft):	78.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade:	79.6 0
O&M Grade: Clock Start/From: Clock To:	0 3
1st Value: 2nd Value:	4.000
Value Percent: Continuous Index: Within 8" of Joint: Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	137.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Continuous Index: Within 8" of Joint:

Remarks:



Code:	TFA
Description:	<b>Tap Factory Active</b>
Distance (ft):	157.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	

Thursday, November 16, 2023



Code:	TF
Description:	Tap Factory

Distance (ft):	197.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Remarks:




Code:	TFA
Description:	Tap Factory Active
Distance (ft):	206.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	



Code:	TF
Description:	Tap Factory

208.5
200.5
0
0
3
4.000



Code:	DSZ
Description:	Deposits Settled Other
Distance (ft):	211.7
Structural Grade:	0

Distance (ft):	211.7
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	5
Clock To:	7
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	misc



Code:	AMH
Description:	Manhole

Distance (ft):	214.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-024