
Profile/Ph	oto Observatio	n Report				RedZone
Date:	03/22/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	): <b>30.0</b>	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie	Honu	PSR:	P-809-030-031
Customer:		Clean Date	e: <b>01/01/</b>	1900	Shape:	С
Street:	EIDER AVE		Flow Cor	ntrol:	Not Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Yard		Tape/Me	edia #:		
Purpose: Maintenance Related		Dia/Height:		8"		
Use:	Sanitary		Material	:	PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details:			Direction of Survey:		Upstream	
US MH:	M-809-031	DS MH:	M-809-030	ר (	Fotal Length Surveyed (ft)	26.2
O&M Index:	0.00	O&M Quick	<:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural (		0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui	ck:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-809-030	



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	AMH Manhole
Distance (ft):	26.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-031