Profile/Photo Observation Report



 Date:
 03/24/2018
 Weather:
 Coding:
 PACP 6.0

 Pipe Length (ft):
 423.3
 Owner:
 NA
 Pre Clean:
 Not Known

P.O.#: Surveyor: **Byrd Fitzgerald** PSR: **P-809-052-053**Customer: **Clean Date: 01/01/1900** Shape: **C**

Street: BRACKEN PKWY Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Sidewalk Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA


Comment:

Location Details: Direction of Survey: Downstream

US MH: M-809-052 DS MH: M-809-053 Total Length Surveyed (ft): 355.1

2.00 2E00 68.00 O&M Index: O&M Quick: O&M Rating: 5.00 5100 5.00 Structural Quick: Structural Rating: Structural Index: 2.09 **512E** 73.00 Overall Index: Overall Quick: Overall Rating:


Position	Code	Observation	Video (sec)	Grade
809-052				
0.	AMH	Manhole	10	NA
.0	MWL	Water Level	21	NA
9.8	TF	Tap Factory	53	NA
\11.0	TF	Tap Factory	69	NA
102.8	TF	Tap Factory	266	NA
<u> 179.0</u>	MGO	General Observation	432	NA
/ 182.4	DAZ(S01)	Deposits Attached Other	450	M 2
194.6	HVV	Hole Void Visible	486	S 5
201.3	TF	Tap Factory	512	NA
203.2	TF	Tap Factory	528	NA
301.1	TF	Tap Factory	735	NA
303.2	TF	Tap Factory	750	NA
353.5	DAZ(F01)	Deposits Attached Other	863	M 2
355.1	AMH	Manhole	881	NA
-				



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: NO

Remarks: M-809-052



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory


Distance (ft): 9.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: TF

Description: **Tap Factory**

Distance (ft): 11.0 Structural Grade: 0 0 O&M Grade: Clock Start/From: 1

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TF

Description: **Tap Factory**


Distance (ft): 102.8 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 11

Clock To:

4.000 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: MGO

Description: General Observation

Distance (ft): 179.0
Structural Grade: 0
O&M Grade: 0


Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: rear camera/cob webs

NO



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 182.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10
Clock To: 2
1st Value:

2nd Value:
Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks: wandering




Code: **HVV**

Description: Hole Void Visible

Distance (ft): 194.6
Structural Grade: 5
O&M Grade: 0
Clock Start/From: 8
Clock To: 10

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: huge



Code: **TF**

Description: Tap Factory

Distance (ft): 201.3
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **TF**

Description: Tap Factory

Distance (ft): 203.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:


1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 301.1
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: TF

Description: **Tap Factory**

Distance (ft): 303.2 Structural Grade: 0 0 O&M Grade: Clock Start/From: 11

Clock To:

1st Value: 4.000


2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

YES

Remarks:

2nd Value:



Code: DAZ

Description: **Deposits Attached Other**

Distance (ft): 353.5 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 10 2 Clock To: 1st Value:

5.000 Value Percent: Continuous Index: F01 Within 8" of Joint: NO

Remarks: wandering



Code: AMH
Description: Manhole

Distance (ft): 355.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-809-053