


Profile/Ph	noto Observatio	n Report			RedZor
Date:	03/23/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	t): <b>161.6</b>	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Justin Gonzal	es PSR:	P-809-057-056
Customer:		Clean Date	: <b>01/01/1900</b>	Shape:	С
Street:	Oak		Flow Control:	Not Controlle	ed
City:	Hobart, IN		Year Renewed		
Location:	Sidewalk		Tape/Media #:		
Purpose:	Maintenance Rela	ated	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	flow is incorrect.				
Location Detai	ils:		Direction of Su	rvey: Downstream	I
US MH:	M-809-056	DS MH:	M-809-057	Total Length Surveyed (	ft): <b>159.0</b>
D&M Index:	0.00	O&M Quick		00 O&M Rating:	0.00
Structural Index	. 0.00	Structural C	Luick: OC	00 Structural Ratin	g: <b>0.00</b>
Overall Index:	0.00	Overall Qui		00 Overall Rating:	0.00






Code: Description:	AMH Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-809-056	




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft):	30.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory
Distance (ft):	45.2
Distance (It).	45.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	

Within 8" of Joint:

Remarks:



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	105.4 0 0 9 4.000



Code:AMHDescription:Manhole

159.0			
0			
0			
1st Value:			
Value Percent:			
NO			
M-809-057			