
Profile/Ph	oto Observatio	n Report			RedZone
Date:	03/23/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	:): <b>72.3</b>	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-809-058-057
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	WILLET AVE		Flow Control:	Not Controlled	ł
City:	Hobart, IN		Year Renewed:		
Location:	Ditch		Tape/Media #:		
Purpose:	Maintenance Rel	ated	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	2nd attempt. flow	w incorrect.			
Location Detai	ls:		Direction of Surv	vey: Upstream	
US MH:	M-809-057	DS MH:	M-809-058	Total Length Surveyed (ft	): <b>71.6</b>
0&M Index:	2.00	O&M Quick:	2A0	0 O&M Rating:	22.00
tructural Index	1.00	Structural Qu	uick: <b>110</b>		1.00
Overall Index:	1.92	Overall Quicl	<: <b>2A1</b>	.1 Overall Rating:	23.00

	Position	Code	Observation	Video (sec)	Grade
M-80	09-058				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
- 1	6.5	DSF(S01)	Deposits Settled Fine	46	M 2
	11.4	DSF(F01)	Deposits Settled Fine	67	M 2
- 1	12.4	TFA	Tap Factory Active	81	NA
	20.3	TFA	Tap Factory Active	110	NA
	20.3	DAGS(S02)	Deposits Attached Grease	122	M 2
	31.1	TF	Tap Factory	155	NA
	42.6	JOM	Joint Offset Medium	190	S 1
5	/ 66.6	TF	Tap Factory	251	NA
e ti	/ 68.2	DAGS(F02)	Deposits Attached Grease	268	M 2
ā	71.6	AMH	Manhole	286	NA
Camera Direction					
M(80	09-057				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-058



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DSF
Description:	Deposits Settled Fine
Distance (ft):	6.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	6
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	



Code:DSFDescription:Deposits Settled Fine

Distance (ft):	11.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	6
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	

Code:


Description:



Distance (ft):	12.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

TFA

**Tap Factory Active** 




Code:TFADescription:Tap Factory Active

Distance (ft):	20.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	DAGS
Description:	Deposits Attached Grease
Distance (ft)	20.2

Distance (ft):	20.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S02
Within 8" of Joint:	NO
Remarks:	




Code:	TF
Description:	Tap Factory

Distance (ft):	31.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	JOM
Description:	Joint Offset Medium

Distance (ft):	42.6	
Structural Grade:	1	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:		



Code:	TF
Description:	Tap Factory

Distance (ft):	66.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	68.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F02
Within 8" of Joint:	NO
Remarks:	



Code: AMH Description: Manhole

Distance (ft):	71.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-057