## **Profile/Photo Observation Report**



Date: 03/23/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 72.3 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-809-058-057 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Oak Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Ditch Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA
Comment: 2nd attempt. flow incorrect.

Location Details: Direction of Survey: **Upstream** 

US MH: M-809-057 DS MH: M-809-058 Total Length Surveyed (ft): 71.6


2.00 2A00 22.00 O&M Rating: O&M Index: O&M Quick: 1.00 1100 1.00 Structural Quick: Structural Rating: Structural Index: 1.92 2A11 23.00 Overall Index: Overall Quick: Overall Rating:

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-809-058

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: DSF

Description: Deposits Settled Fine



Distance (ft): 6.5
Structural Grade: 0

O&M Grade: 2
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 11.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:

Code: TFA

Description: Tap Factory Active



Distance (ft): 12.4
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 20.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS


Description: Deposits Attached Grease

Distance (ft): 20.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

Value Percent: 5.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks:

2nd Value:



Code: **TF** 

Description: Tap Factory

Distance (ft): 31.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **JOM** 

Description: Joint Offset Medium


Distance (ft): 42.6
Structural Grade: 1
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 66.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 68.2
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 4

1st Value:

Value Percent: 5.000
Continuous Index: F02
Within 8" of Joint: NO

Remarks:

2nd Value:



Code: AMH
Description: Manhole

Distance (ft): 71.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-809-057