Profile/Ph	oto Observation	Report			RedZon
Date:	03/21/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft)	: 227.9	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Honu	PSR:	P-902-053-059
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	E 36TH ST & RUSH	PL	Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	10"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Place	2
Category:	NA				
Comment:					
Location Detail	s:		Direction of Sur	vey: Upstream	
US MH:	M-902-053	DS MH:	M-902-059	Total Length Surveyed (f	t): 220.9
0&M Index:	2.50	O&M Quick:	382	28 O&M Rating:	40.00
tructural Index:	2.00	Structural Qu	iick: 280		16.00
Overall Index:	2.33	Overall Quick	c: <b>38</b> 2	2B Overall Rating:	56.00

	Position	Code	Observation	Video (sec)	Grade
M(902-05	59				
	.0	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
Ň	3.2	MWLS(S01)	Water Level Sag	39	S 2
	8.1	DAGS(S02)	Deposits Attached Grease	62	M 2
	42.5	MWLS(F01)	Water Level Sag	145	S 2
	47.4	DAGS(F02)	Deposits Attached Grease	168	M 2
	126.7	TF	Tap Factory	340	NA
	130.0	TF	Tap Factory	359	NA
	185.0	TF	Tap Factory	480	NA
<u>5</u>	220.9	АМН	Manhole	564	NA
Camera Direction	3				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-902-059



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MWLS Water Level Sag
Distance (ft):	3.2
Structural Grade:	2
O&M Grade:	3
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	




Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	8.1
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S02
Within 8" of Joint:	NO
Remarks:	

100	flighten f	
		a state of the sta

Code:	MWLS
Description:	Water Level Sag

Distance (ft):	42.5
Structural Grade:	2
O&M Grade:	3
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	



Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	47.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F02
Within 8" of Joint:	NO
Remarks:	

Code:



Description:	Tap Factory
Distance (ft):	126.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	


TF



Code:TFDescription:Tap Factory

130.0
0
0
10
4.000

Code:



Description:	Tap Factory
Distance (ft):	185.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

TF

Code: Description:

AMH Manhole



Distance (ft):	220.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-902-053