## **Profile/Photo Observation Report**



Date: 03/21/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 181.7 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: PSR: P-902-058-057 Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: RUSH PL Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-902-057 DS MH: M-902-058 Total Length Surveyed (ft): 72.3

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
02-058				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
31.3	TF	Tap Factory	95	NA
39.2	LFAC	Lining Failure Abandoned Connection	125	NA
66.5	TF	Tap Factory	193	NA
72.3	MSA	Abandoned Survey	216	NA

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade: Clock Start/From:	0
Clock To: 1st Value:	
2nd Value: Value Percent:	
Continuous Index: Within 8" of Joint: Remarks:	NO M-902-058

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: TF
Description: Tap Factory

Distance (ft): 31.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: LFAC

Description: Lining Failure Abandoned

Connection

Distance (ft): 39.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF** 

Description: Tap Factory

Distance (ft): 66.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 72.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: debris