

## Profile/Photo Observation Report




|                   |                   |             |                        |            |                      |
|-------------------|-------------------|-------------|------------------------|------------|----------------------|
| Date:             | <b>03/26/2018</b> | Weather:    |                        | Coding:    | <b>PACP 6.0</b>      |
| Pipe Length (ft): | <b>332.1</b>      | Owner:      | <b>NA</b>              | Pre Clean: | <b>Not Known</b>     |
| P.O.#:            |                   | Surveyor:   | <b>Justin Gonzales</b> | PSR:       | <b>P-902-063-062</b> |
| Customer:         |                   | Clean Date: | <b>01/01/1900</b>      | Shape:     | <b>C</b>             |

|             |                       |               |                       |
|-------------|-----------------------|---------------|-----------------------|
| Street:     | <b>OFF E 37TH AVE</b> | Flow Control: | <b>Not Controlled</b> |
| City:       | <b>Hobart, IN</b>     | Year Renewed: |                       |
| Location:   | <b>Other</b>          | Tape/Media #: |                       |
| Purpose:    | <b>Not Known</b>      | Dia/Height:   | <b>10"</b>            |
| Use:        | <b>Sanitary</b>       | Material:     | <b>PVC</b>            |
| Drain Area: | <b>NA</b>             | Lining:       |                       |
| Category:   | <b>NA</b>             |               |                       |
| Comment:    |                       |               |                       |

|                   |                  |                             |                   |
|-------------------|------------------|-----------------------------|-------------------|
| Location Details: |                  | Direction of Survey:        | <b>Downstream</b> |
| US MH:            | <b>M-902-063</b> | DS MH:                      | <b>M-902-062</b>  |
|                   |                  | Total Length Surveyed (ft): | <b>325.1</b>      |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <b>0.00</b> | O&M Quick:        | <b>0000</b> | O&M Rating:        | <b>0.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b> |
| Overall Index:    | <b>0.00</b> | Overall Quick:    | <b>0000</b> | Overall Rating:    | <b>0.00</b> |

|  | Position | Code | Observation | Video (sec) | Grade |
|--|----------|------|-------------|-------------|-------|
|  | .0       | AMH  | Manhole     | 10          | NA    |
|  | .0       | MWL  | Water Level | 21          | NA    |
|  | 314.5    | MWL  | Water Level | 662         | NA    |
|  | 325.1    | AMH  | Manhole     | 694         | NA    |

Code: AMH

Description: Manhole



Distance (ft): .0

Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: M-902-063



| Code:               | MWL         |
|---------------------|-------------|
| Description:        | Water Level |
| Distance (ft):      | .0          |
| Structural Grade:   | 0           |
| O&M Grade:          | 0           |
| Clock Start/From:   |             |
| Clock To:           |             |
| 1st Value:          |             |
| 2nd Value:          |             |
| Value Percent:      | 5.000       |
| Continuous Index:   |             |
| Within 8" of Joint: | NO          |
| Remarks:            |             |

---



| Code:               | MWL         |
|---------------------|-------------|
| Description:        | Water Level |
| Distance (ft):      | 314.5       |
| Structural Grade:   | 0           |
| O&M Grade:          | 0           |
| Clock Start/From:   |             |
| Clock To:           |             |
| 1st Value:          |             |
| 2nd Value:          |             |
| Value Percent:      | 20.000      |
| Continuous Index:   |             |
| Within 8" of Joint: | NO          |
| Remarks:            |             |

---



|                     |                  |
|---------------------|------------------|
| Code:               | <b>AMH</b>       |
| Description:        | <b>Manhole</b>   |
| Distance (ft):      | <b>325.1</b>     |
| Structural Grade:   | <b>0</b>         |
| O&M Grade:          | <b>0</b>         |
| Clock Start/From:   |                  |
| Clock To:           |                  |
| 1st Value:          |                  |
| 2nd Value:          |                  |
| Value Percent:      |                  |
| Continuous Index:   |                  |
| Within 8" of Joint: | <b>NO</b>        |
| Remarks:            | <b>M-902-062</b> |