

Profile/Photo Observation Report



Date:	04/25/2018	Weather:		Coding:	PACP 4.2
Pipe Length (ft):	39.0	Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	2004	Surveyor:	SAN	PSR:	P-902-066-060
Customer:	Red Zone	Clean Date:		Shape:	C

Street:	3622 Rush Pl	Flow Control:	Not Controlled
City:	Hobart In	Year Renewed:	
Location:	Yard	Tape/Media #:	Deliverable 1
Purpose:	Routine Assessment	Dia/Height:	6"
Use:	Sanitary	Material:	VCP
Drain Area:	Northeast	Lining:	
Category:	NA		
Comment:	432-1. PSR incorrect in video overlay.		
Location Details:	Edge of street	Direction of Survey:	Upstream
US MH:	M-902-066	DS MH:	M-902-060
		Total Length Surveyed (ft):	39.0

O&M Index:	3.00	O&M Quick:	3200	O&M Rating:	6.00
Structural Index:	2.50	Structural Quick:	3311	Structural Rating:	10.00
Overall Index:	2.67	Overall Quick:	3511	Overall Rating:	16.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	37	NA
	.0	MWL	Water Level	51	NA
	1.5	JOM	Joint Offset Medium	114	S 1
	4.5	MWLS(S01)	Water Level Sag	156	S 3
	10.9	MWLS(F01)	Water Level Sag	250	S 3
	10.9	MWL	Water Level	261	NA
	31.7	CM	Crack Multiple	369	S 3
	31.7	MWLS(S02)	Water Level Sag	388	S 3
	38.4	MWLS(F02)	Water Level Sag	727	S 3
	38.4	MGO	General Observation	769	NA
	39.0	AMH	Manhole	845	NA



Code: **AMH**
 Description: **Manhole**

Distance (ft): **.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **M-902-060**



Code: **MWL**
Description: **Water Level**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **JOM**
Description: **Joint Offset Medium**

Distance (ft): **1.5**
Structural Grade: **1**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **MWLS**
Description: **Water Level Sag**

Distance (ft): **4.5**
Structural Grade: **3**
O&M Grade: **3**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **50.000**
Continuous Index: **S01**
Within 8" of Joint: **NO**
Remarks:



Code: **MWLS**
Description: **Water Level Sag**

Distance (ft): **10.9**
Structural Grade: **3**
O&M Grade: **3**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **50.000**
Continuous Index: **F01**
Within 8" of Joint: **NO**
Remarks:



Code:	MWL
Description:	Water Level
Distance (ft):	10.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	CM
Description:	Crack Multiple
Distance (ft):	31.7
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	9
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: **MWLS**
 Description: **Water Level Sag**

Distance (ft): **31.7**
 Structural Grade: **3**
 O&M Grade: **3**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **35.000**
 Continuous Index: **S02**
 Within 8" of Joint: **NO**
 Remarks:



Code: **MWLS**
 Description: **Water Level Sag**

Distance (ft): **38.4**
 Structural Grade: **3**
 O&M Grade: **3**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **35.000**
 Continuous Index: **F02**
 Within 8" of Joint: **NO**
 Remarks:



Code:	MGO
Description:	General Observation
Distance (ft):	38.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	debris in manhole



Code:	AMH
Description:	Manhole
Distance (ft):	39.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-902-066