Profile/Photo Observation Report



Date: 04/10/2018 Weather: Coding: **PACP 4.2** Pipe Length (ft): 145.9 Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: 2004 Surveyor: SAN PSR: P-902-045-039 Customer: **Red Zone** Clean Date: Shape:

Street: 3815 34th Pl Flow Control: Not Controlled

City: **Hobart In** Year Renewed:

Location: Light Highway Tape/Media #: Deliverable 1

Purpose: Routine Assessment Dia/Height: 15"
Use: Sanitary Material: PVC

Drain Area: **unknown** Lining:

Category: NA

Comment: 401-1/ Incomplete line-needs cleaning.

Location Details: Flows from street through yards Direction of Survey: Downstream

US MH: M-902-076 DS MH: M-902-039 Total Length Surveyed (ft): 5.0

O&M Index:	5.00	_O&M Quick:	5100	O&M Rating:	5.00
Structural Index:	0.00	_Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	5.00	Overall Quick:	5100	Overall Rating:	5.00

	Position	Code	Observation	Video (sec)	Grade
M(902)0	76				
	.0	AMH	Manhole	12	NA
	\0	MWL	Water Level	56	NA
-11	5.0	DSZ	Deposits Settled Other	165	M 5
-11	5.0	MSA	Abandoned Survey	208	NA
Camera Direction					



Code:	AMH
Description:	Manhole
D: (61)	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	P902-076



Code: MWL Description: **Water Level** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 45.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: DSZ Description: **Deposits Settled Other** Distance (ft): 5.0 Structural Grade: 0 O&M Grade: 5 Clock Start/From: 3 Clock To: 9 1st Value: 2nd Value: Value Percent: 75.000 Continuous Index: Within 8" of Joint: NO Remarks: debris



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: line needs cleaned