


Profile/Ph	noto Observatio	n Report			RedZon R 0 B 0 T I C S
Date:	03/23/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	t): <b>320.2</b>	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-903-006-011
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	E 38TH AVE & SPI	E 38TH AVE & SPENCER PL		Not Controlled	ł
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ils:		Direction of Surv	vey: Downstream	
US MH:	M-903-006	DS MH:	M-903-011	Total Length Surveyed (ft	): <b>18.2</b>
0&M Index:	3.00	O&M Quick:	310	00 O&M Rating:	3.00
tructural Index	. 0.00	Structural Q		Ū	0.00
Overall Index:	3.00	Overall Quic	.k: <b>310</b>		3.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-903-006



Code: Description:

MWL

Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 30.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code:	RMJ
Description:	<b>Roots Medium Joint</b>

Distance (ft):	18.2
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	1
Clock To:	6
1st Value:	
2nd Value:	
Value Percent:	40.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:

MSA Abandoned Survey

Distance (ft):	18.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	roots