Date:	04/02/2018	Weather:		C	oding:	PACP 6.0
Pipe Length (ft)	: <b>199.1</b>	Owner:	NA	P	re Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	P	SR:	P-903-014-015
Customer:		Clean Date:	01/01/1900	SI	hape:	с
Street:	N SHELBY PL		Flow Control:	N	ot Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Other		Tape/Media #:			
Purpose:	Not Known		Dia/Height:	8"	ı	
Use:	Sanitary		Material:	V	СР	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details	5:		Direction of Sur	vey: U	pstream	
US MH:	M-903-015	DS MH:	M-903-014	Total Length	Surveyed (ft):	149.5
D&M Index:	2.00	O&M Quick:	200	00 O&N	1 Rating:	46.00
Structural Index:	4.00	Structural Qu			ctural Rating:	4.00
Overall Index:	2.08	Overall Quicl		20	all Rating:	50.00

	Position	Code	Observation	Video (sec)	Grade
M(903-	014				
$\vdash$	0. //	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	3.3	TF	Tap Factory	41	NA
	<u>_</u>	ТВ	Tap Break-in	60	NA
_	23.5	MGO	General Observation	112	NA
	36.0	DAGS(S01)	Deposits Attached Grease	148	M 2
_	79.0	TF	Tap Factory	246	NA
	81.3	TF	Tap Factory	262	NA
_	121.1	FM	Fracture Multiple	353	S 4
5	138.3	TF	Tap Factory	400	NA
ecti	149.5	MSA	Abandoned Survey	436	NA
Į D	149.5	DAGS(F01)	Deposits Attached Grease	447	M 2
Camera Direction					
M <del>(</del> 903-	015				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-903-014



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	3.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	тв
Description:	Tap Break-in

5.5
0
0
2
4.000




Code: Description:	MGO General Observation
Distance (ft):	23.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	REAR CAMERA



Code:DAGSDescription:Deposits Attached Grease


Distance (ft):	36.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	



TF Tap Factory
79.0
0
0
2
4.000




Code:	TF
Description:	Tap Factory
Distance (ft):	81.3
Distance (ft):	01.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	FM
Description:	Fracture Multiple
Distance (ft):	121.1
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Cleak Ter	4

Odivi Ulaue.	U	
Clock Start/From:	8	
Clock To:	4	
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	YES	
Remarks:		



Code:	TF
Description:	Tap Factory

Distance (ft):	138.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Code:	MSA
Description:	Abandoned Survey



Distance (ft):	149.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	UNDER WATER



Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	149.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	