Profile/Photo Observation Report



Date: 10/03/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 194.9 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: Justin Gonzales PSR: P-903-023-022
Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN BRANDT ST & RUSH Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-903-022 DS MH: M-903-023 Total Length Surveyed (ft): 145.8

312D 1.97 57.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 1.97 312D 57.00 Overall Quick: Overall Rating: Overall Index:

Code	Observation	Video (sec)	Grade
AMH	Manhole	10	NA
MWL	Water Level	21	NA
DAGS(S01)	Deposits Attached Grease	75	M 2
TF	Tap Factory	97	NA
MGO	General Observation	156	NA
TF	Tap Factory	196	NA
DAZ	Deposits Attached Other	219	M 2
TF	Tap Factory	287	NA
TFA	Tap Factory Active	340	NA
RFJ	Roots Fine Joint	363	M 1
MGO	General Observation	374	NA
RFJ	Roots Fine Joint	392	M 1
TF	Tap Factory	441	NA
RMJ	Roots Medium Joint	455	M 3
MSA	Abandoned Survey	475	NA
DAGS(F01)	Deposits Attached Grease	486	M 2
	AMH MWL DAGS(S01) TF MGO TF DAZ TF TFA RFJ MGO RFJ TF RMJ MSA	AMH Manhole MWL Water Level DAGS(S01) Deposits Attached Grease TF Tap Factory MGO General Observation TF Tap Factory DAZ Deposits Attached Other TF Tap Factory TFA Tap Factory TFA Tap Factory Active RFJ Roots Fine Joint MGO General Observation RFJ Roots Fine Joint TF Tap Factory RMJ Roots Medium Joint MSA Abandoned Survey	AMH Manhole 10 MWL Water Level 21 DAGS(S01) Deposits Attached Grease 75 TF Tap Factory 97 MGO General Observation 156 TF Tap Factory 196 DAZ Deposits Attached Other 219 TF Tap Factory 287 TFA Tap Factory 340 RFJ Roots Fine Joint 363 MGO General Observation 374 RFJ Roots Fine Joint 392 TF Tap Factory 441 RMJ Roots Medium Joint 455 MSA Abandoned Survey 475

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-903-022		

 AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.

Continuous Index:


Within 8" of Joint: NO

Remarks:

10.000

Code: DAGS

Description: Deposits Attached Grease



Distance (ft): 21.2

Structural Grade: 0

O&M Grade: 2


Clock Start/From: 7

Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks: WANDER



Code: **TF**

Description: Tap Factory

Distance (ft): 26.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: General Observation



Distance (ft): 49.7
Structural Grade: 0


O&M Grade: 0

O&M Grade: Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: LARVAE ON LENS



Code: **TF**

Description: Tap Factory

Distance (ft): 63.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000**

DAZ

Deposits Attached Other

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code:





Distance (ft): 68.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: **TF**

Description: Tap Factory

Distance (ft): 96.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 116.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 120.5
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 2
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MGO

Description: General Observation

Distance (ft): 120.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: FRONT LENS OBSTRUCTED



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 123.6
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory


Distance (ft): 141.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 142.5
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 145.8
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: ROBOT HAS STOPPED



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 145.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER