Profile/Photo Observation Report



Date: 10/02/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 225.3 Owner: NA Pre Clean: **Not Known** P.O.#: **Justin Gonzales** PSR: P-903-026-025 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Rand St. Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-903-025 DS MH: M-903-026 Total Length Surveyed (ft): 225.3

2.33 7.00 O&M Index: O&M Quick: O&M Rating: 3.85 **514A** 50.00 Structural Quick: Structural Rating: Structural Index: 3.56 57.00 514A Overall Quick: Overall Rating: Overall Index:

l	Position	Code	Observation	Video (sec)	Grade
903-025					
	0	AMH	Manhole	10	NA
\.	0	MWL	Water Level	21	NA
1	16.7	RFJ	Roots Fine Joint	66	M 1
	58.7	FM	Fracture Multiple	162	S 4
/E	52.2	FM	Fracture Multiple	182	S 4
	53.4	TFD	Tap Factory Defective	196	M 2
	55.9	FM	Fracture Multiple	213	S 4
	58.9	MCU	Camera Underwater	231	M 4
7	76.8	FM	Fracture Multiple	259	S 4
1	78.8	TF	Tap Factory	275	NA
<u> </u>	79.5	FM	Fracture Multiple	289	S 4
3///	35.0	FM	Fracture Multiple	312	S 4
<u></u>	90.7	FM	Fracture Multiple	335	S 4
<u>- </u>	95.4	FM	Fracture Multiple	357	S 4
<u> </u>	99.5	FM	Fracture Multiple	377	S 4
	104.2	CH3	Crack Longitudinal Hinge, 3	398	S 5
] \]	112.4	TF	Tap Factory	427	NA
]	114.3	FM	Fracture Multiple	443	S 4
 	118.0	TF	Tap Factory	463	NA
$\left \right \left \right \left \right $	157.6	TF	Tap Factory	554	NA
	176.7	CL	Crack Longitudinal	605	S 2
	178.7	TF	Tap Factory	621	NA
2	203.2	FL	Fracture Longitudinal	681	S 3
1/2	205.6	TF	Tap Factory	698	NA
7	208.5	TF	Tap Factory	716	NA
2	225.3	AMH	Manhole	762	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Clock Start/From:

Within 8" of Joint: NO

Remarks: M-903-025



Code: MWL
Description: Water Level


Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 16.7
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 3

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FM

Description: Fracture Multiple

Distance (ft): 58.7
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 10

Clock To: 5

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Remarks:

Within 8" of Joint:

YES



Description: Fracture Multiple

Distance (ft): 62.2
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 7

Clock To: 5

1st Value: 2

2nd Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 63.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

MOUTH OF TAP BROKEN



Description: Fracture Multiple

Distance (ft): 65.9
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: MCU

Description: Camera Underwater



Distance (ft): 68.9
Structural Grade: 0
O&M Grade: 4

Clock Start/From:

Clock Start/From
Clock To:
1st Value:
2nd Value:
Value Percent:

Continuous Index:

Within 8" of Joint: NO



Description: Fracture Multiple

Distance (ft): 76.8
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 12
Clock To: 3


1st Value:
2nd Value:
Value Percent:
Continuous Index:

Mithin Of of Laint.

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 78.8
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Fracture Multiple

Distance (ft): 79.5
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

YES



Code: FM


Description: Fracture Multiple

Distance (ft): 85.0
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Description: Fracture Multiple

Distance (ft): 90.7
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 7


Clock To: 5

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FM

Description: Fracture Multiple

Distance (ft): 95.4
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:

Remarks:

Continuous Index: Within 8" of Joint:



Description: Fracture Multiple

Distance (ft): 99.5
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CH3

Description: Crack Longitudinal Hinge, 3

Distance (ft): 104.2

Structural Grade: 5

O&M Grade: 0


Clock Start/From: 9

Clock To: 3

1st Value: 2

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **TF**

Description: Tap Factory

Distance (ft): 112.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: **FM**

Description: Fracture Multiple

4.000




Distance (ft): 114.3
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **TF**

Description: Tap Factory

Distance (ft): 118.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: **Tap Factory**

Distance (ft): 157.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:




Code: CL

Description: Crack Longitudinal

Distance (ft): 176.7
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 9

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory


Distance (ft): 178.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:



Code: FL

Description: Fracture Longitudinal

Distance (ft): 203.2
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 205.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 208.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 225.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-903-026