Profile/Photo Observation Report



Date: 10/02/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 225.3 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Justin Gonzales** PSR: P-903-026-025

Customer: Clean Date: 01/01/1900 Shape: C

Street: **E RAND ST** Flow Control: **Not Controlled**

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-903-025 DS MH: M-903-026 Total Length Surveyed (ft): 219.6

2.00 3121 6.00 O&M Index: O&M Quick: O&M Rating: 3.65 5346 62.00 Structural Quick: Structural Rating: Structural Index: 3.40 5346 68.00 Overall Quick: Overall Rating: Overall Index:

Position	Code	Observation	Video (sec)	Grade
03-025				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
17.5	RFJ	Roots Fine Joint	67	M 1
59.0	FM	Fracture Multiple	162	S 4
60.8	FM	Fracture Multiple	177	S 4
62.5	FM	Fracture Multiple	192	S 4
// 62.9	TFD	Tap Factory Defective	204	M 2
65.2	FM	Fracture Multiple	220	S 4
67.7	MWLS	Water Level Sag	236	S 3
75.5	CM	Crack Multiple	263	S 3
77.5	TF	Tap Factory	279	NA
77.7	CM	Crack Multiple	291	S 3
79.3	CH3	Crack Longitudinal Hinge, 3	305	S 5
85.0	CM	Crack Multiple	328	S 3
88.1	FM	Fracture Multiple	346	S 4
91.1	FH3	Fracture Longitudinal Hinge, 3	363	S 5
93.6	FM	Fracture Multiple	380	S 4
97.3	CM	Crack Multiple	398	S 3
99.8	CL	Crack Longitudinal	415	S 2
102.2	CH3	Crack Longitudinal Hinge, 3	431	S 5
109.5	TF	Tap Factory	457	NA
111.4	CM	Crack Multiple	472	S 3
115.3	TF	Tap Factory	492	NA
153.5	TF	Tap Factory	579	NA
173.7	TF	Tap Factory	631	NA
197.5	FL	Fracture Longitudinal	690	S 3
200.1	TF	Tap Factory	708	NA
202.7	TF	Tap Factory	725	NA
219.6	AMH	Manhole	770	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: M-903-025

NO



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 17.5
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FM

Description: Fracture Multiple

Distance (ft): 59.0
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 12

Clock To: 5

1st Value: 2

2nd Value: Value Percent:

Within 8" of Joint: YES

Remarks:

Continuous Index:



Code: FM

Description: Fracture Multiple

Distance (ft): 60.8
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 7

Clock To: 5

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FM

Description: Fracture Multiple

Distance (ft): 62.5
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 7

Clock To: 5

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Description: Tap Factory Defective


Distance (ft): 62.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

1st Value: **5.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: MOUTH OF TAP BROKEN



Code: FM

Description: Fracture Multiple

Distance (ft): 65.2
Structural Grade: 4


O&M Grade: 0

Clock Start/From: 7

Clock To: 5

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: MWLS

Description: Water Level Sag

Distance (ft): 67.7
Structural Grade: 3
O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 40.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:




Code: CM

Description: Crack Multiple

Distance (ft): 75.5
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 3
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Description: Tap Factory


Distance (ft): 77.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:


Remarks:



Code: CM

Description: Crack Multiple

Distance (ft): 77.7 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 8 3 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES



Code: CH3


Description: Crack Longitudinal Hinge, 3

Distance (ft): 79.3
Structural Grade: 5
O&M Grade: 0
Clock Start/From: 9
Clock To: 3
1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

YES




Code: CM

Description: Crack Multiple

Distance (ft): 85.0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 8
Clock To: 3
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: FΜ

Description: **Fracture Multiple**


Distance (ft): 88.1 Structural Grade: 4 0 O&M Grade: Clock Start/From: 8 Clock To: 3 1st Value: 2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES




Code: FH3

Description: Fracture Longitudinal Hinge, 3

Distance (ft): 91.1 Structural Grade: 5 O&M Grade: 0 Clock Start/From: 9 3 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

YES



Code: FM

Description: Fracture Multiple

Distance (ft): 93.6
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: CM


Description: Crack Multiple



Distance (ft): 97.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 3

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 99.8
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CH3

Description: Crack Longitudinal Hinge, 3

Distance (ft): 102.2

Structural Grade: 5

O&M Grade: 0

Clock Start/From: 9

Clock To: 3


1st Value: 2

2nd Value: Value Percent: Continuous Index:

Remarks:

Within 8" of Joint:

YES



Description: Tap Factory


Distance (ft): 109.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




Code: CM

Description: Crack Multiple

Distance (ft): 111.4
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 9
Clock To: 3
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Description: Tap Factory

Distance (ft): 115.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 153.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 173.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: FL

Description: Fracture Longitudinal



Distance (ft): 197.5
Structural Grade: 3


O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

YES



Description: Tap Factory

Distance (ft): 200.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 202.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: AMH
Description: Manhole

Distance (ft): 219.6
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-903-026