## **Profile/Photo Observation Report**



Date: 10/02/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 173.2 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Justin Gonzales** PSR: P-903-025-028

Customer: Clean Date: 01/01/1900 Shape:

**E RAND ST** Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed: Tape/Media #: Location: **Light Highway** 

Purpose: **Routine Assessment** Dia/Height: 12" Use: Sanitary Material: **VCP** 

Overall Quick:

NA Lining: Drain Area:

NA Category:

Overall Index:

Comment: **Location Details:** Direction of Survey:

US MH: Total Length Surveyed (ft): M-903-025 DS MH: M-903-028 160.2

1.92 2E13 69.00 O&M Index: O&M Quick: O&M Rating: 2.71 19.00 Structural Quick: Structural Rating: Structural Index: 2.05 88.00

**Downstream** 

Overall Rating:

.0         MWL         Water Level         21         N.           .0         DAGS(S01)         Deposits Attached Grease         32         M           .0         FM         Fracture Multiple         44         S           3.8         RFJ         Roots Fine Joint         64         M           14.9         RFJ         Roots Fine Joint         98         M           16.2         FL         Fracture Longitudinal         112         S           17.9         RFJ         Roots Fine Joint         128         M           19.8         FL         Fracture Longitudinal         143         S           22.3         FL         Fracture Longitudinal         160         S           45.2         TF         Tap Factory         217         N.           52.0         CL         Crack Longitudinal         243         S           81.2         TFI         Tap Factory Intruding         313         M           91.8         CL         Crack Longitudinal         346         S           106.5         CL         Crack Longitudinal         387         S           133.1         TF         Tap Factory         452         N.	Position	Code	Observation	Video (sec)	Grade
.0       AMH       Manhole       10       N.         .0       MWL       Water Level       21       N.         .0       DAGS(S01)       Deposits Attached Grease       32       M         .0       FM       Fracture Multiple       44       S.         3.8       RFJ       Roots Fine Joint       64       M         14.9       RFJ       Roots Fine Joint       98       M         16.2       FL       Fracture Longitudinal       112       S         17.9       RFJ       Roots Fine Joint       128       M         19.8       FL       Fracture Longitudinal       143       S         22.3       FL       Fracture Longitudinal       160       S         45.2       TF       Tap Factory       217       N         52.0       CL       Crack Longitudinal       243       S         81.2       TFI       Tap Factory Intruding       313       M         91.8       CL       Crack Longitudinal       346       S         106.5       CL       Crack Longitudinal       387       S         133.1       TF       Tap Factory       452       N	03-025				
0         DAGS(S01)         Deposits Attached Grease         32         M           .0         FM         Fracture Multiple         44         S           3.8         RFJ         Roots Fine Joint         64         M           14.9         RFJ         Roots Fine Joint         98         M           16.2         FL         Fracture Longitudinal         112         S           17.9         RFJ         Roots Fine Joint         128         M           19.8         FL         Fracture Longitudinal         143         S           22.3         FL         Fracture Longitudinal         160         S           45.2         TF         Tap Factory         217         N           52.0         CL         Crack Longitudinal         243         S           81.2         TFI         Tap Factory Intruding         313         M           91.8         CL         Crack Longitudinal         346         S           106.5         CL         Crack Longitudinal         387         S           133.1         TF         Tap Factory         452         N		AMH	Manhole	10	NA
1.0   FM   Fracture Multiple   44   S   S   S   S   RFJ   Roots Fine Joint   64   M   M   M   M   M   M   M   M   M	.0	MWL	Water Level	21	NA
3.8   RFJ   Roots Fine Joint   64   M     14.9   RFJ   Roots Fine Joint   98   M     16.2   FL   Fracture Longitudinal   112   S     17.9   RFJ   Roots Fine Joint   128   M     19.8   FL   Fracture Longitudinal   143   S     22.3   FL   Fracture Longitudinal   160   S     45.2   TF   Tap Factory   217   N     52.0   CL   Crack Longitudinal   243   S     81.2   TFI   Tap Factory Intruding   313   M     91.8   CL   Crack Longitudinal   346   S     106.5   CL   Crack Longitudinal   387   S     133.1   TF   Tap Factory   452   N	0.//	DAGS(S01)	Deposits Attached Grease	32	M 2
14.9       RFJ       Roots Fine Joint       98       M         16.2       FL       Fracture Longitudinal       112       S         17.9       RFJ       Roots Fine Joint       128       M         19.8       FL       Fracture Longitudinal       143       S         22.3       FL       Fracture Longitudinal       160       S         45.2       TF       Tap Factory       217       N         52.0       CL       Crack Longitudinal       243       S         81.2       TFI       Tap Factory Intruding       313       M         91.8       CL       Crack Longitudinal       346       S         106.5       CL       Crack Longitudinal       387       S         133.1       TF       Tap Factory       452       N	0.	FM	Fracture Multiple	44	S 4
16.2         FL         Fracture Longitudinal         112         S           17.9         RFJ         Roots Fine Joint         128         M           19.8         FL         Fracture Longitudinal         143         S           22.3         FL         Fracture Longitudinal         160         S           45.2         TF         Tap Factory         217         N           52.0         CL         Crack Longitudinal         243         S           81.2         TFI         Tap Factory Intruding         313         M           91.8         CL         Crack Longitudinal         346         S           106.5         CL         Crack Longitudinal         387         S           133.1         TF         Tap Factory         452         N	3.8	RFJ	Roots Fine Joint	64	M 1
17.9         RFJ         Roots Fine Joint         128         M           19.8         FL         Fracture Longitudinal         143         S           22.3         FL         Fracture Longitudinal         160         S           45.2         TF         Tap Factory         217         N           52.0         CL         Crack Longitudinal         243         S           81.2         TFI         Tap Factory Intruding         313         M           91.8         CL         Crack Longitudinal         346         S           106.5         CL         Crack Longitudinal         387         S           133.1         TF         Tap Factory         452         N	14.9	RFJ	Roots Fine Joint	98	M 1
19.8         FL         Fracture Longitudinal         143         S           22.3         FL         Fracture Longitudinal         160         S           45.2         TF         Tap Factory         217         N           52.0         CL         Crack Longitudinal         243         S           81.2         TFI         Tap Factory Intruding         313         M           91.8         CL         Crack Longitudinal         346         S           106.5         CL         Crack Longitudinal         387         S           133.1         TF         Tap Factory         452         N	16.2	FL	Fracture Longitudinal	112	S 3
22.3   FL   Fracture Longitudinal   160   S	17.9	RFJ	Roots Fine Joint	128	M 1
45.2   TF   Tap Factory   217   N.	19.8	FL	Fracture Longitudinal	143	S 3
S2.0   CL   Crack Longitudinal   243   S	22.3	FL	Fracture Longitudinal	160	S 3
81.2         TFI         Tap Factory Intruding         313         M           91.8         CL         Crack Longitudinal         346         S           106.5         CL         Crack Longitudinal         387         S           133.1         TF         Tap Factory         452         N	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	TF	Tap Factory	217	NA
91.8         CL         Crack Longitudinal         346         S           106.5         CL         Crack Longitudinal         387         S           133.1         TF         Tap Factory         452         N.	52.0	CL	Crack Longitudinal	243	S 2
106.5 CL Crack Longitudinal 387 S  133.1 TF Tap Factory 452 NA	81.2	TFI	Tap Factory Intruding	313	M 2
133.1 TF Tap Factory 452 N.	91.8	CL	Crack Longitudinal	346	S 2
	106.5	CL	Crack Longitudinal	387	S 2
7450 0 ANNU AA L L	133.1	TF	Tap Factory	452	NA
/ 160.2 AMH Manhole 518 N.	160.2	AMH	Manhole	518	NA
160.2 DAGS(F01) Deposits Attached Grease 529 M	160.2	DAGS(F01)	Deposits Attached Grease	529	M 2

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-903-025

AMH



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO



Code: DAGS

Description: **Deposits Attached Grease** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 5 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES Remarks: WANDER



Code: FM

Description: Fracture Multiple

Distance (ft): .0
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 10
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:


YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 3.8 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 10 2 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 14.9
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 11
Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FL

Description: Fracture Longitudinal

Distance (ft): 16.2
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 17.9
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 9
Clock To: 4

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES




Code: FL

Description: Fracture Longitudinal

Distance (ft): 19.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: FL

Description: Fracture Longitudinal

Distance (ft): 22.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 45.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: CL

Description: Crack Longitudinal

Distance (ft): 52.0
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFI** 

Description: Tap Factory Intruding

Distance (ft): 81.2
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 11

Clock To:

 1st Value:
 4.000

 2nd Value:
 0.500

Value Percent: Continuous Index: Within 8" of Joint:



Code: CL

Description: Crack Longitudinal

Distance (ft): 91.8
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 106.5
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 11

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 133.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 160.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-903-028



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 160.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER