Profile/Photo Observation Report

Use:



Date: 04/03/2018 Weather: Coding: **PACP 6.0** Pipe Length (ft): 139.2 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-903-029-013 Surveyor:

Customer: Clean Date: 01/01/1900 Shape:

E RAND ST & N HOBART RD Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed:

Other Tape/Media #: Location: Purpose: **Not Known** Dia/Height: 12" Sanitary Material: **VCP**

NA Lining: Drain Area:

NA Category:


Comment: **Location Details:** Direction of Survey: **Downstream**

US MH: M-803-013 Total Length Surveyed (ft): M-903-029 DS MH: 40.1

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 4.00 4.00 Structural Index: Structural Quick: Structural Rating: 4.00 4.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
M(903-)0	29				
	.0	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
- 11	\\1.6	FM	Fracture Multiple	36	S 4
- 11	40.1	MSA	Abandoned Survey	125	NA
Camera Direction					
Came					
M(803)0	13				

Code:



Description:	Manhole	
Distance (ft): Structural Grade:	.0 0	
O&M Grade: Clock Start/From:	0	
Clock To: 1st Value: 2nd Value:		
Value Percent: Continuous Index:		
Within 8" of Joint: Remarks:	NO M-903-029	

AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:


Within 8" of Joint:

Remarks:

NO

Code: FM

Description: Fracture Multiple



Distance (ft): 1.6
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 10

Clock To: 3

1st Value:


2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 40.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: debris under water