Profile/Photo Observation Report



Date: 03/22/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 216.2 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-903-035-034 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: n hobart rd Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Upstream**

US MH: M-903-034 DS MH: M-903-035 Total Length Surveyed (ft): 5.6

4.00 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 4.00 4.00 Overall Quick: Overall Rating: Overall Index:

Pos	sition Code	Observation	Video (sec)	Grade
1(903-)035				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
0.	MCU	Camera Underwater	33	M 4
5.6	MSA	Abandoned Survey	55	NA
Ш				
ш				
ш				
ш				
ш				
,				
ш				
ш				
ш				
ш				
Ш				

Code:

Description:



D: 1 (6)	•
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-903-035

AMH

Manhole



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

Code:

100.000

NO

MCU



Description: **Camera Underwater**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 4 Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: UNDER WATER