Profile/Photo Observation Report



Date: 03/21/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 222.9 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: PSR: P-903-053-037 Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: 37th ave Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-903-037 DS MH: M-903-053 Total Length Surveyed (ft): 1.3

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

P	osition	Code	Observation	Video (sec)	Grade
M(903-053					
0.)	AMH	Manhole	10	NA
0.)	MWL	Water Level	21	NA
1.	.3	MSA	Abandoned Survey	35	NA
Camera Direction M-903-037					

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-903-037		

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: MSA

Description: **Abandoned Survey**



Distance (ft): 1.3 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-903-053, line plugged