


Data	02/20/2018	\\/aathaw		Cadinari	
Date:	03/20/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft):	181.4	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	JUSTIN GONZA		P-903-051-052
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	OFF E 38TH PL		Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	10"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Details:			Direction of Surv	vey: Upstream	
US MH: N	1-903-052	DS MH:	M-903-051	Total Length Surveyed (f	t): <b>197.8</b>
0&M Index:	2.00	O&M Quick:	210	0 O&M Rating:	2.00
Structural Index:	0.00	Structural Qu	uick: 000		g: <b>0.00</b>
Overall Index:	2.00	Overall Quic			2.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-903-051




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	


Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	60.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: MWL Description: Water Level

Distance (ft):	193.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	197.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-903-052