Profile/Photo Observation Report



Date: 03/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 212.0 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: PSR: P-903-052-053 Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: OFF E 38TH PL Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: **M-903-053** DS MH: **M-903-052** Total Length Surveyed (ft): **16.6**

5100 5.00 5.00 O&M Rating: O&M Index: O&M Quick: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 5.00 5100 5.00 Overall Index: Overall Quick: Overall Rating:

3 .0	АМН			
.0	$\Lambda \Lambda \Lambda \sqcup$			
	LIIVII	Manhole	10	NA
.0	MWL	Water Level	21	NA
16.1	RBB	Roots Ball Barrel	65	M 5
16.6	MSA	Abandoned Survey	77	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-903-053

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: RBB Description: **Roots Ball Barrel**



Distance (ft): 16.1 Structural Grade: 0

O&M Grade: 5 Clock Start/From: 12 Clock To: 12

1st Value: 2nd Value:

Value Percent: 90.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 16.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: root ball infiltration