Profile/Photo Observation Report



Date: 03/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 212.0 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-903-052-053 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: 37th ave Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: **NA**Comment:

Location Details: Direction of Survey: **Downstream**

US MH: **M-903-053** DS MH: **M-903-052** Total Length Surveyed (ft): **16.6**

5100 5.00 5.00 O&M Rating: O&M Index: O&M Quick: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 5.00 5100 5.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
M(903-)0	53				
	.0	АМН	Manhole	10	NA
- 11	\\.0	MWL	Water Level	21	NA
- 11	16.1	RBB	Roots Ball Barrel	65	M 5
ш	16.6	MSA	Abandoned Survey	77	NA
Camera Direction					
M(903)0	52				

Code:



Description:	Manhole
Distance (ft): Structural Grade: O&M Grade:	.0 0 0
Clock Start/From: Clock To: 1st Value:	·
2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	NO
Remarks:	M-903-053

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

12

Code: RBB

Description: Roots Ball Barrel



Distance (ft): 16.1
Structural Grade: 0
O&M Grade: 5
Clock Start/From: 12

1st Value: 2nd Value:

Clock To:

Value Percent: 90.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 16.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: root ball infiltration