Profile/Photo Observation Report



Date: 04/02/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 155.3 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: Jen Costello PSR: P-903-020-021

Customer: Clean Date: 01/01/1900 Shape: C

Street: Rand St. Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment:

Location Details: Direction of Survey: Upstream

US MH: M-903-202 DS MH: M-903-021 Total Length Surveyed (ft): 17.4

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 3.00 3100 3.00 Structural Quick: Structural Rating: Structural Index: 3100 3.00 3.00 Overall Quick: Overall Rating: Overall Index:

Position	Code	Observation	Video (sec)	Grade
1(903-)021				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	22	NA
6.6	FL	Fracture Longitudinal	46	S 3
17.4	MSA	Abandoned Survey	80	NA
1-903-202				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-903-021		

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

30.000

NO

Code: FL

Description: **Fracture Longitudinal**



Distance (ft): 6.6

Structural Grade: 3 O&M Grade: 0 Clock Start/From: 2

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MSA

Description: **Abandoned Survey**

17.4 Distance (ft): Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

NO Remarks: **OVERTURNED**