Profile/Photo Observation Report

0.00

Overall Quick:

Overall Index:



0.00

Date: 05/04/2018 Weather: **PACP 4.2** Coding: Pipe Length (ft): 385.0 Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: 2004 PSR: P-904-008-009 Surveyor: SAN **Red Zone** Clean Date: Customer: Shape: 166 Fraser Ln Flow Control: **Not Controlled** Street: City: **Hobart In** Year Renewed: Easement/Right of Way Tape/Media #: Deliverable 1 Location: Purpose: **Routine Assessment** Dia/Height: 18" **PVC** Use: Sanitary Material: Northeast Drain Area: Lining: NA Category: Comment: 448-1 **Location Details:** Edge of field Direction of Survey: Upstream M-904-008 US MH: DS MH: M-904-009 Total Length Surveyed (ft): 385.0 0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating:

0000

Overall Rating:

Thursday, May 4, 2023 1

Position	Code	Observation	Video (sec)	Grade
л (904) 009				
0.	AMH	Manhole	42	NA
0.	MWL	Water Level	69	NA
13.0	MGO	General Observation	133	NA
385.0	AMH	Manhole	667	NA

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade: Clock Start/From:	0
Clock To: 1st Value:	
2nd Value: Value Percent:	
Continuous Index: Within 8" of Joint: Remarks:	NO M-904-009

 AMH

Thursday, May 4, 2023 2



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 13.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: debris under flow

Thursday, May 4, 2023 3



Code: AMH
Description: Manhole

Distance (ft): 385.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: M-904-008

NO

Thursday, May 4, 2023 4