Profile/Photo Observation Report



Date: 04/06/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 222.1 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-904-037-038 Surveyor: **Mark Ruby**

Customer: Clean Date: 01/01/1900 Shape: C

Street: Brandt Pl. Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment: NULL - CNL - REV - NULL - CNL

Location Details: Direction of Survey: **Upstream**

US MH: M-904-038 DS MH: M-904-037 Total Length Surveyed (ft): 94.3

4.00 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 4.00 4.00 Overall Quick: Overall Rating: Overall Index:

	Code	Observation	Video (sec)	Grade
904-037				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
23.8	TF	Tap Factory	80	NA
/40.8	TF	Tap Factory	126	NA
88.6	MCU	Camera Underwater	234	M 4
94.3	MSA	Abandoned Survey	257	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-904-037		

 AMH



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:


Remarks:

10.000

NO

4.000

Code: TF Description: **Tap Factory**




Distance (ft): 23.8 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 8

Clock To: 1st Value:

2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 40.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 5

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MCU

Description: Camera Underwater

Distance (ft): 88.6
Structural Grade: 0
O&M Grade: 4
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: N

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 94.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: NCU