Date:	04/05/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)	: <b>303.9</b>	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello		PSR:	P-904-063-062
Customer:		Clean Date:	01/01/1900		Shape:	С
Street:	Shelby St.		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed	:		
Location:	Other		Tape/Media #			
Purpose:	Not Known		Dia/Height:		8"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details	:		Direction of Su	irvey:	Downstream	
US MH:	M-904-062	DS MH:	M-904-063	Total I	ength Surveyed (ft)	166.6
D&M Index:	3.00	O&M Quick:	4	131	O&M Rating:	9.00
Structural Index:	0.00	Structural Qu	uick: 0	000	Structural Rating:	0.00
Overall Index:	3.00	Overall Quic		131	Overall Rating:	9.00

	Position	Code	Observation	Video (sec)	Grade
M-904	-062				
	.0	AMH	Manhole	10	NA
- 11	.0	MWL	Water Level	21	NA
		DSZ	Deposits Settled Other	38	M 3
- 11	4.1	MWL	Water Level	52	NA
	13.3	MWL	Water Level	82	NA
	18.4	MWL	Water Level	104	NA
	41.6	MWL	Water Level	161	NA
- 11	80.7	TFC	Tap Factory Capped	252	NA
	141.4	DSF	Deposits Settled Fine	385	M 2
5	146.7	MWL	Water Level	407	NA
Camera Direction	153.6	TFC	Tap Factory Capped	434	NA
		MWL	Water Level	463	NA
ner	161.6	MCU	Camera Underwater	474	M 4
Car	166.6	MSA	Abandoned Survey	496	NA



\_\_\_\_



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-904-062



Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DSZ
Description:	Deposits Settled Other

Distance (ft):	2.5
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	4
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	MISC



Distance (ft):	4.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	MWL
Description:	Water Level
Distance (ft):	13.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	100.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Distance (ft):	18.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	40.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code:

Remarks:



Description:	Water Level
Distance (ft):	41.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO

MWL



Code:TFCDescription:Tap Factory Capped

Distance (ft):	80.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	DSF
Description:	Deposits Settled Fine

Distance (ft):	141.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	5
Clock To:	7
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	MWL
Description:	Water Level

Distance (ft):	146.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	40.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	TFC
Description:	Tap Factory Capped
<b>D</b> (1)	
Distance (ft):	153.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Distance (ft):	161.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	100.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	MCU
Description:	Camera Underwater

Distance (ft):	161.6	
Structural Grade:	0	
O&M Grade:	4	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:		



Code: Description: MSA Abandoned Survey

Distance (ft):	166.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	UNDER WATER