## **Profile/Photo Observation Report**



Date: 10/04/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 303.9 Owner: NA Pre Clean: **Not Known** P.O.#: **Justin Gonzales** PSR: P-904-063-062 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Shelby St. Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 8"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream** 


US MH: M-904-062 DS MH: M-904-063 Total Length Surveyed (ft): 237.8

2.25 119.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 2.24 121.00 Overall Quick: Overall Rating: Overall Index:

.0 .0 .0 8.5 14.8 80.2 152.8	AMH MWL DAGS(S01) MWLS TFC	Manhole Water Level Deposits Attached Grease	10 21 49	NA NA
.0 .0 8.5 14.8 80.2 /152.8	MWL DAGS(S01) MWLS	Water Level Deposits Attached Grease	21	
8.5 14.8 80.2 /152.8	DAGS(S01) MWLS	Deposits Attached Grease		NA
14.8 80.2 /152.8	MWLS		40	
80.2 /152.8			49	M 2
152.8	TFC	Water Level Sag	73	S 2
/	11.0	Tap Factory Capped	216	NA
//	TFC	Tap Factory Capped	373	NA
/ 163.4	MCU(S02)	Camera Underwater	406	M 4
182.2	MCU(F02)	Camera Underwater	455	M 4
227.2	MCU(S03)	Camera Underwater	556	M 4
237.8	MSA	Abandoned Survey	589	NA
237.8	MCU(F03)	Camera Underwater	600	M 4
237.8	DAGS(F01)	Deposits Attached Grease	611	M 2

Code:


Description:



Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-904-062

**AMH** 

Manhole



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

3.000

NO

Code: DAGS

Description: Deposits Attached Grease



Distance (ft): 8.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES
Remarks: WANDER



Code: MWLS

Description: Water Level Sag

Distance (ft): 14.8
Structural Grade: 2
O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 15.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TFC** 

Description: Tap Factory Capped

Distance (ft): 80.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFC

Description: Tap Factory Capped

Distance (ft): 152.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: MCU

Description: Camera Underwater



Distance (ft): 163.4 Structural Grade: 0

O&M Grade: 4

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: S02
Within 8" of Joint: NO



Code: MCU

Description: Camera Underwater

Distance (ft): 182.2
Structural Grade: 0
O&M Grade: 4

Clock Start/From:


Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: F02
Within 8" of Joint: NO

Remarks:

Code: MCU

Description: Camera Underwater




Distance (ft): 227.2
Structural Grade: 0

O&M Grade: **4** Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: **S03** Within 8" of Joint: **NO** 



Code: MSA

Description: Abandoned Survey

Distance (ft): 237.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: MCU

Code: MCU

Description: Camera Underwater




Distance (ft): 237.8
Structural Grade: 0
O&M Grade: 4

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: F03
Within 8" of Joint: NO



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 237.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER