Profile/Photo Observation Report



Date: 10/04/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 285.4 Owner: NA Pre Clean: **Not Known** P.O.#: **Justin Gonzales** PSR: P-904-072-063 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: SHELBY ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:

Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 8"

Use: Sanitary Material: VCP

Drain Area: NA Lining: Category: NA

Category: NA
Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-904-063 DS MH: M-904-072 Total Length Surveyed (ft): 287.1

2.00 2100 106.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 108.00 Overall Rating: Overall Index: Overall Quick:

	Position	Code	Observation	Video (sec)	Grade
904-0	63				
\checkmark	0. 📈	AMH	Manhole	10	NA
	\0	MWL	Water Level	21	NA
	20.4	DAGS(S01)	Deposits Attached Grease	73	M 2
-	41.4	MWL	Water Level	127	NA
	64.8	TFC	Tap Factory Capped	185	NA
	69.5	MWL	Water Level	207	NA
	113.8	CL	Crack Longitudinal	307	S 2
	114.2	ТВ	Tap Break-in	320	NA
	// 140.4	IS	Infil Stain	384	NA
	/ 147.2	TFC	Tap Factory Capped	409	NA
	//163.2	IS	Infil Stain	453	NA
	183.4	IS	Infil Stain	505	NA
	230.9	TFC	Tap Factory Capped	611	NA
/	241.4	IS	Infil Stain	644	NA
	246.6	RPR	Repair Point Pipe Replaced	666	NA
	249.7	TF	Tap Factory	684	NA
	259.2	TF	Tap Factory	716	NA
	287.1	DAGS(F01)	Deposits Attached Grease	784	M 2
	287.1	AMH	Manhole	795	NA

Code:

Description:



Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-904-063

AMH

Manhole



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

2nd Value:

5.000

NO



Code: DAGS

Description: **Deposits Attached Grease**

Distance (ft): 20.4 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 5 1st Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES Remarks:

WANDER



Code: MWL

Description: Water Level

Distance (ft): 41.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


10.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:



Code: **TFC**

Description: Tap Factory Capped

Distance (ft): 64.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL

Description: Water Level

Distance (ft): 69.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 15.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO




Code: CL

Description: Crack Longitudinal

Distance (ft): 113.8
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 10

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:



Code: TB

Description: Tap Break-in

Distance (ft): 114.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




Code: IS

Description: Infil Stain

Distance (ft): 140.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 7
Clock To: 10
1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

hin 8" of Joint: YES



Code: TFC

Description: Tap Factory Capped

Distance (ft): 147.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: IS


Description: Infil Stain

Distance (ft): 163.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10
Clock To: 3
1st Value:
2nd Value:

Continuous Index: Within 8" of Joint:

Value Percent:

thin 8" of Joint: YES



Code: IS

Description: Infil Stain


Distance (ft): 183.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFC**


Description: Tap Factory Capped

Distance (ft): 230.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: IS

Description: Infil Stain


Distance (ft): 241.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11
Clock To: 4

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RPR

Description: Repair Point Pipe Replaced


Distance (ft): 246.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: PVC



Code: **TF**

Description: Tap Factory


Distance (ft): 249.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 259.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 287.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER



Code: AMH
Description: Manhole

Distance (ft): 287.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-904-072