Profile/Photo Observation Report




Profile/Photo Observation Report							
Date: Pipe Length (ft P.O.#:	608	Weather: Owner: Surveyor:	City of Hobart M. Pielacha	Coding: Pre Clean: PSR:	PACP 6.0 No Pre-Cleaning P-905-001-003		
Customer:	City of Hobart	Clean Date:		Shape:	С		
Street:	Off State Road		Flow Control:	Not Controlled			
City:	Hobart, IN		Year Renewed:				
Location:	Sidewalk		Tape/Media #:	DEP 608			
Purpose:	Routine Assessment		Dia/Height:	18"			
Use:	Sanitary		Material:	PVC			
Drain Area:			Lining:				
Category:	NA						
Comment:	5-21-2018						
Location Details:			Direction of Survey	: Upstream			
US MH:	M-905-003	DS MH: N	И-905-001	Total Length Surveyed (ft)	: 179.1		
O&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00		
Structural Index:	0.00	— Structural Quic	ck: 0000	Structural Rating:	0.00		
Overall Index:	3.00	Overall Quick:	3100	Overall Rating:	3.00		

Thursday, May 4, 2023

	Position	Code	Observation	Video (sec)	Grade
M(905-)00	01				
	.0	AMH	Manhole	0	NA
	\.0	MWL	Water Level	7	NA
- 11	132.6	TF	Tap Factory	282	NA
- 11	179.1	DSF	Deposits Settled Fine	585	M 3
- 11	179.1	MSA	Abandoned Survey	592	NA
Camera Direction					

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-905-003

 AMH

Thursday, May 4, 2023 2



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

/alue Percent: **15.000**

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 132.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

Thursday, May 4, 2023 3



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 179.1
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 179.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: sediment

Thursday, May 4, 2023 4