Profile/Photo Observation Report



Date: 04/24/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 212.3 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-905-008-007 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Sullivan Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Ditch Tape/Media #:

Purpose: Maintenance Related Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: **Debris at 207'.**

Location Details: Direction of Survey: **Downstream**

US MH: M-905-007 DS MH: M-905-008 Total Length Surveyed (ft): 208.6

2.00 2200 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2200 4.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
905-	007				
\bigvee	0. //	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
Ш	22.6	TF	Tap Factory	78	NA
	25.3	TF	Tap Factory	96	NA
ш	54.7	TF	Tap Factory	168	NA
ш	54.7	DAE	Deposits Attached Encrustation	180	M 2
	142.2	TF	Tap Factory	368	NA
ш	206.8	DSF	Deposits Settled Fine	510	M 2
ш	208.6	MSA	Abandoned Survey	525	NA
	11				

Code:

Description:



.0
0
0
NO
M-905-007

AMH

Manhole



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To:

1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

10.000

NO

Remarks:

Code: TF

Description: **Tap Factory**

Distance (ft): 22.6 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 1

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

4.000

Distance (ft): 25.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:


1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Tap Factory



Distance (ft): 54.7
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 54.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 10

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:



Code: TF

Description: Tap Factory

Distance (ft): 142.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 206.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 208.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: dsf