## **Profile/Photo Observation Report**



Date: 04/24/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 368.5 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-905-033-011 Surveyor:

01/01/1900

Shape:

Street: S SHELBY ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Parking Lot Tape/Media #:

Clean Date:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment:

Customer:

Location Details: Direction of Survey: Upstream

US MH: M-905-011 DS MH: M-905-033 Total Length Surveyed (ft): 23.3

2.00 2500 10.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2500 10.00 Overall Rating: Overall Index: Overall Quick:

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-905-033

AMH



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO

Code: DAGS

Description: **Deposits Attached Grease** 



Distance (ft): .0 Structural Grade: 0 O&M Grade: 2

Clock Start/From: 8 Clock To: 4 1st Value:

2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: NO

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 23.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:

Code: MSA

Description: Abandoned Survey



Distance (ft): 23.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: dags