## **Profile/Photo Observation Report**



Date: 04/14/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 266.1 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-906-002-003 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Capitol Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Sidewalk Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: possible roots at joint at 133'.


Location Details: Direction of Survey: Downstream

US MH: M-906-002 DS MH: M-906-003 Total Length Surveyed (ft): 134.6

3329 2.07 29.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.07 3329 29.00 Overall Quick: Overall Rating: Overall Index:


1	Position	Code	Observation	Video (sec)	Grade
906-002					
	0	AMH	Manhole	10	NA
\\\.	0	MWL	Water Level	21	NA
\.	0	DAGS(S01)	Deposits Attached Grease	32	M 2
3	31.1	TFA	Tap Factory Active	106	NA
<b> </b>   /3	32.2	RFJ	Roots Fine Joint	120	M 1
	47.2	DAGS(F01)	Deposits Attached Grease	162	M 2
1	105.2	RMJ	Roots Medium Joint	290	M 3
	105.3	DAR	Deposits Attached Ragging	302	M 3
<b></b> / [1	127.5	RFJ	Roots Fine Joint	358	M 1
	133.3	RMJ	Roots Medium Joint	381	M 3
	134.6	MSA	Abandoned Survey	396	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-906-002		

 $\mathsf{AMH}$ 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:


5.000

NO

Remarks:

Code: DAGS


Description: **Deposits Attached Grease** 



Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: NO



Code: TFA

Description: Tap Factory Active


Distance (ft): 31.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 32.2

Structural Grade: 0

O&M Grade: 1

Clock Start/From: 10

Clock To: 11

1st Value: 2

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 47.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:

Code: RMJ

Description: Roots Medium Joint



Distance (ft): 105.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 3
Clock To: 4

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES



Code: DAR

Description: Deposits Attached Ragging

Distance (ft): 105.3
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 6
Clock To: 10

1st Value: 2nd Value:


Value Percent: 20.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES




Code: RFJ

Description: Roots Fine Joint

Distance (ft): 127.5
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 4
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 133.3
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 9
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:


Within 8" of Joint:

Remarks:

YES

Code: MSA

Description: Abandoned Survey



Distance (ft): 134.6 Structural Grade: 0

O&M Grade: **0** 

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: ROOTS