Profile/Photo Observation Report



Date: 04/12/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 362.2 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-906-006-005 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: E 9TH PL & DUCK CREEK CT Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA
Comment: sediment on sidewall at 9'.

Location Details: Direction of Survey: Upstream

US MH: M-906-006 DS MH: M-906-005 Total Length Surveyed (ft): 9.3

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Rating: Overall Index: Overall Quick:


	Position	Code	Observation	Video (sec)	Grade
n (906) 0	05				
	0.	АМН	Manhole	10	NA
	\\	MWL	Water Level	21	NA
	9.3	DAGS	Deposits Attached Grease	52	M 2
	9.3	MSA	Abandoned Survey	63	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade: O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Continuous Index:	
Within 8" of Joint: Remarks:	NO M-906-005

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000


Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: DAGS

Description: Deposits Attached Grease



Distance (ft): 9.3
Structural Grade: 0

O&M Grade: 2
Clock Start/From: 8
Clock To: 4


1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 9.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: dags