
Profile/Ph	oto Observatio	n Report			RedZone
Date:	04/11/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft)	: 389.5	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-907-001-002
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	Capitol		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Ditch		Tape/Media #:		
Purpose:	Maintenance Rel	ated	Dia/Height:	12"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Place	
Category:	NA				
Comment:	heavy blk silt at 19'incorrect flow				
Location Detail	s:		Direction of Surv	vey: Upstream	
US MH:	M-907-002	DS MH:	M-907-001	Total Length Surveyed (ft)	: 20.5
0&M Index:	0.00	O&M Quick:	000	0 O&M Rating:	0.00
tructural Index:	0.00	Structural Qu	uick: 000		0.00
Overall Index:	0.00	Overall Quic	k: 000	0 Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-907-001



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:

Code:



Description:	Abandoned Survey
Distance (ft):	20.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	debris under water

MSA