


Profile/Ph	oto Observatio	n Report				RedZone
Date:	04/11/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 401.2	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello		PSR:	P-907-005-006
Customer:		Clean Date	: 01/01/1900		Shape:	с
Street:	S HOBART RD		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Ditch		Tape/Media #:			
Purpose:	Maintenance Rela	ated	Dia/Height:		12"	
Use:	Sanitary		Material:		Ρ٧Ϲ	
Drain Area:	NA		Lining:		Cured in Place	
Category:	NA					
Comment:	flow incorrect. bla	ack silt sludge at	80'.			
Location Detai	ls:		Direction of Sur	rvey:	Downstream	
US MH:	M-907-006	DS MH:	M-907-005	Total Leng	gth Surveyed (ft):	81.6
0&M Index:	0.00	O&M Quick	. 00	00 O	&M Rating:	0.00
tructural Index:	0.00	Structural Q	uick: 00	00 St	tructural Rating:	0.00
Overall Index:	0.00	Overall Quid	ck: 00	00 O	verall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-907-006



Code: MWL Description: Water Level

.0
0
0
5.000
NO



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	81.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	debris under water