
Profile/Ph	oto Observatio	n Report				RedZone
Date: Pipe Length (ft P.O.#: Customer:	03/28/2018): 172.1	Weather: Owner: Surveyor: Clean Date	NA Selasie Honu : 01/01/1900		Coding: Pre Clean: PSR: Shape:	PACP 6.0 Not Known P-910-028-018 C
Street:	River Pointe CC		Flow Control:		Not Controlled	-
City:	Hobart, IN		Year Renewed	:		
Location:	Ditch		Tape/Media #			
Purpose:	Maintenance Rela	ated	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	Flow direction wr	ong. Redeploym	ient.			
Location Detai	ls:		Direction of Su	rvey:	Upstream	
US MH:	M-910-018	DS MH:	M-910-028	Tota	al Length Surveyed (ft):	170.3
D&M Index:	2.00	O&M Quick	22	200	O&M Rating:	4.00
Structural Index:	0.00	Structural Q	uick: 0	000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quid	:k: 2 2	200	Overall Rating:	4.00





Code: Description:	DAGS Deposits Attached Grease
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	




Code: AMH Description: Manhole

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-910-028



Code: Description:	MWL Water Level
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Tuesday, December 8, 2020



Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	7.7
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	170.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-910-018