## **Profile/Photo Observation Report**



Date:	10/21/2021	Weather:		Codin	σ. ΒΛ	CP 6.0
Pipe Length (fi		Owner:	Hobart, IN	Pre Cl	_	t Known
P.O.#:	946_1	Surveyor:	M. Pielacha	PSR:		910-029-028
Customer:	Hobart, IN	Clean Date:	Will Ficiatina	Shape		,10 015 010
Street:	Country Club Lot		Flow Control:			
City:	Hobart, IN		Year Renewed:			
Location:	Parking Lot		Tape/Media #:	946		
Purpose:	Routine Assessmer	nt	Dia/Height:	8"		
Use:	Sanitary		Material:	CAS		
Drain Area:			Lining:			
Category:	NA					
Comment:						
Location Detai	ils:		Direction of Sur	vey: <b>Upstre</b>	eam	
US MH:	M-910-28	DS MH:	M-910-29	Total Length Surv	veyed (ft):	10.7
0&M Index:	5.00	O&M Quick:	510	00 O&M Rat	ing:	5.00
tructural Index	1.00	Structural Qu	ick: <b>12</b> 0		_	2.00
Overall Index:	2.33	Overall Quick	E44		_	7.00

Thursday, May 4, 2023 1

Position	Code	Observation	Video (sec)	Grade
210-29				
.0	AMH	Manhole	0	NA
0.	MWL	Water Level	47	NA
\.0	SRI(S01)	Surface Roughness Increased	71	S 1
10.7	SRI(F01)	Surface Roughness Increased	120	S 1
10.7	OBZ	Obstacle Other	125	M 5
10.7	MSA	Abandoned Survey	133	NA



Code: Description:	AMH Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-910-29		

Thursday, May 4, 2023 2



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: SRI

Description: **Surface Roughness Increased** 

Distance (ft): .0 Structural Grade: 1 O&M Grade: 0 Clock Start/From: 7 Clock To: 5 1st Value: 2nd Value: Value Percent:

Continuous Index: **S01** Within 8" of Joint: YES

Remarks:

3 Thursday, May 4, 2023



Code: SRI

Description: Surface Roughness Increased

Distance (ft): 10.7
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: NO

Remarks:



Code: OBZ

Description: Obstacle Other

Distance (ft): 10.7
Structural Grade: 0
O&M Grade: 5
Clock Start/From: 4
Clock To: 8
1st Value:

Value Percent: **35.000** 

Continuous Index:

2nd Value:

Within 8" of Joint: NO Remarks: Debris

Thursday, May 4, 2023



Code: MSA

Description: Abandoned Survey

Distance (ft): 10.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: heavy debris

Thursday, May 4, 2023 5