Profile/Photo Observation Report



Date: 04/14/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 328.9 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: Jen Costello PSR: P-503-045-062

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 38TH PL Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-503-062 DS MH: M-503-045 Total Length Surveyed (ft): 308.3

2.05 240.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.05 240.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
503	-062				
\geq	.0	AMH	Manhole	10	NA
		MWL	Water Level	21	NA
ш	3.4	IW	Infil Weeper	39	M 2
	√\\\8.1	DAE(S02)	Deposits Attached Encrustation	60	M 2
	¬∭8.1	IW(S01)	Infil Weeper	71	M 2
ш	\\\ 18.6	ID	Infil Dripper	103	M 3
	34.2	ID	Infil Dripper	146	M 3
	_\ \\\\49.9	ID	Infil Dripper	189	M 3
Н	-√\ 80.8	DAE(F02)	Deposits Attached Encrustation	262	M 2
ш	97.3	DAE	Deposits Attached Encrustation	306	M 2
	118.1	DAE	Deposits Attached Encrustation	359	M 2
ш	122.9	DAE	Deposits Attached Encrustation	380	M 2
	143.9	DAE	Deposits Attached Encrustation	433	M 2
	149.2	DAE	Deposits Attached Encrustation	455	M 2
	170.1	DAE(S03)	Deposits Attached Encrustation	508	M 2
ш	212.4	RFJ	Roots Fine Joint	604	M 1
ш	259.0	ID	Infil Dripper	709	M 3
ш	259.0	DAE	Deposits Attached Encrustation	720	M 4
		TF	Tap Factory	744	NA
Ш	265.2	DAE	Deposits Attached Encrustation	755	M 2
Ш	277.2	ID	Infil Dripper	790	M 3
Ш	298.5	MMC	Material Change	845	NA
	300.4	TFA	Tap Factory Active	862	NA
	- ///302.2	MMC	Material Change	879	NA
	308.3	DAE(F03)	Deposits Attached Encrustation	902	M 2
	308.3	IW(F01)	Infil Weeper	914	M 2
	308.3	MSA	Abandoned Survey	925	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-062



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0


Clock Start/From:

Clock To:
1st Value:
2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: IW

Description: Infil Weeper


Distance (ft): 3.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 9

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE


Description: Deposits Attached Encrustation

Distance (ft): 8.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 11
1st Value:

Value Percent: 10.000
Continuous Index: S02
Within 8" of Joint: YES

Remarks:

2nd Value:



Code: IW

Description: Infil Weeper

Distance (ft): 8.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:

Continuous Index: **S01**Within 8" of Joint: **YES**

Remarks:




Code: ID

Description: Infil Dripper

Distance (ft): 18.6
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 1
Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **ID**

Description: Infil Dripper


Distance (ft): 34.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: ID

Description: Infil Dripper

Distance (ft): 49.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 11
Clock To:
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES



Description: Deposits Attached Encrustation

Distance (ft): 80.8
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 7

Clock To: 11


1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F02
Within 8" of Joint: YES

Remarks:

Code: DAE

Description: Deposits Attached Encrustation




Distance (ft): 97.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES



Description: Deposits Attached Encrustation

Distance (ft): 118.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

1st Value: 2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 122.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Description: Deposits Attached Encrustation

Distance (ft): 143.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE


Description: Deposits Attached Encrustation

Distance (ft): 149.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES



Description: Deposits Attached Encrustation

Distance (ft): 170.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S03
Within 8" of Joint: YES

Remarks:

Code: RFJ


Description: Roots Fine Joint



Distance (ft): 212.4
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 1
Clock To: 3
1st Value:
2nd Value:
Value Percent:
Continuous Index:

YES

Within 8" of Joint:



Code: ID

Description: Infil Dripper


Distance (ft): 259.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 11

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation


Distance (ft): 259.0
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 7
Clock To: 12
1st Value:

2nd Value:

Value Percent: **30.000**

Continuous Index:

Within 8" of Joint: YES



Code: **TF**

Description: Tap Factory

Distance (ft): 265.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**


2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Deposits Attached Encrustation

4




Distance (ft): 265.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Code: ID

Description: Infil Dripper

Distance (ft): 277.2

Structural Grade: 0

O&M Grade: 3

Clock Start/From: 11

Clock To: 1

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MMC

Description: Material Change

Distance (ft): 298.5
Structural Grade: 0
O&M Grade: 0

O&M Grade: Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: PVC



Code: TFA

Description: Tap Factory Active

4.000

Distance (ft): 300.4
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 2

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MMC


Description: Material Change

Distance (ft): 302.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: vcp



Description: Deposits Attached Encrustation

Distance (ft): 308.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: F03
Within 8" of Joint: YES

Remarks:

Code: IW

Description: Infil Weeper




Distance (ft): 308.3 Structural Grade: 0

O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 308.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: debris under water