Profile/Photo Observation Report



Profile/Photo Observation Report								
Date:	04/28/2018	Weather:			Coding:	PACP 6.0		
Pipe Length (ft	t):	Owner:	City of Hob	art	Pre Clean:	Not Known		
P.O.#:	256	Surveyor:	B. Helbling		PSR:			
Customer:	City of Hobart	Clean Date:			Shape:	С		
Street:	East 10th Street		Flow Control:		Not Controlled			
City:	Hobart, IN		Year Renewe	d:				
Location:	Sidewalk		Tape/Media	# :	DEP256			
Purpose:	Routine Assessment		Dia/Height:		12"			
Use:	Sanitary		Material:		PVC			
Drain Area:			Lining:					
Category:	NA							
Comment:	5-21-2018							
Location Detai	ls:		Direction of S	urvey:	Downstream			
US MH:	M-806-045	DS MH:	M-806-061		Total Length Surveyed (ft):	347.9		
O&M Index:	0.00	O&M Quick:	(0000	O&M Rating:	0.00		
Structural Index	0.00	Structural Qu	uick:	0000	Structural Rating:	0.00		
Overall Index:	0.00	Overall Quicl		0000	Overall Rating:	0.00		

Thursday, May 4, 2023

Positio	n Code	Observation	Video (sec)	Grade
И (806 -)045				
.0	AMH	Manhole	0	NA
0.	MWL	Water Level	12	NA
347.9	AMH	Manhole	1835	NA
M-806-061				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-806-045		

 AMH

Thursday, May 4, 2023 2



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: AMH
Description: Manhole



Distance (ft): 347.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-806-061

Thursday, May 4, 2023 3