
Profile/Photo Observation Report




Profile/Prioto Observation Report								
Date:	02/20/2024	Weather:		Coding:	PACP 7.0			
Pipe Length (ft)): 211.0	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning			
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-708-009.2-009.1			
Customer:	City of Hobart	Clean Date:	02/17/2024	Shape:	С			
Street:	S LAKE PARK AVE		Flow Control:	Not Controlled				
City:	Hobart, IN		Year Renewed:					
Location:	Parking Lot		Tape/Media #:					
Purpose:	Sewer System Eva	aluation Survey (SS	Dia/Height:	10"				
Use:	Sanitary Sewage F	Pipe	Material:	PVC				
Drain Area:			Lining:	None				
Category:	NA							
Comment:								
Location Detail	s:		Direction of Survey	: Upstream				
US MH:	M-708-009.2	DS MH:	M-708.009.1	Total Length Surveyed (ft):	211.4			
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00			
Structural Index:	0.00	Structural Qui	ick: 0000	Structural Rating:	0.00			
Overall Index:	0.00	Overall Quick		Overall Rating:	0.00			

	Position	Code	Observation	Video (sec)	Grade
1- 7 08.0	09.1				
	0. /	AMH	Manhole	0	NA
ш	0.	MWL	Miscellaneous Water Level	70	NA
ш	28.9	TF	Tap Factory	221	NA
	211.4	AMH	Manhole	1169	NA
ш					
ш					
ш					
.					
Camera Direction					
era					
Can					
ш					
ш					
ш					
ш					
ш					
ш					
ш					
1-\$08-9	09.2				



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708.009.1



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

3.000



Code: **TF**

Description: Tap Factory

Distance (ft): 28.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 211.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

 $Continuous\ Index:$

Within 8" of Joint: NO

Remarks: M-708-009.2